CORRES. CONTROL OUTGOING LTR NO.

23 RF 2735

_		
DICT	T	£ MC
DIST.	C1**	<u> </u>
BENJAMIN A.	1_	!
BERMAN, H.S.		
BRANCH, D.B.	Ţ	L_
CARNIVAL, G.J.		Γ_
COPP. R.D.	†	\vdash
DAVIS, J.G.	+	₩
	+	
FERRERA, D.W.	╄	;
HANNI, B.J.	_	ــــ
HARMAN, L. K.		┺
HEALY, T.J.	1_	ᆫ
HILBIG, J.G.		L
IDEKER, E.H.	T	Г
KERSH, J.M.	_	\vdash
KIPSY, W.A.	+	-
	+	\vdash
1110	┼	⊢
LEE, E.M.	╀	_
MANN, H.P.		
MARX, G.E.		\Box
McDONALD, M.M.	1	_
MCKENNA F.G.	\vdash	_
MONTROSE, J.K.	1	
MCRGAN, R.V.	1	\vdash
	-	-
POTTER, G.L.	-	_
PIZZUTO, V.M.	-	_
RILEY, J.H.	لنا	
SANDLIN, N.B.		
SHEPLER RI		
STEWART, D.L.		
SULLIVAN, M.T.		-
SWANSON E R	-	-
WILKINSON, R.B.	$\overline{}$	_
		-
WILSON, J. M.	\vdash	—
ZANE, J. O.	\Box	<u> </u>
Benedetti KL	X	
Smith TA		_
Mart EC	ואנ	_
Arna I MR	1	
MACON MID	М	_
	╌	_
	Н	_
	∺	_
		
	Πİ	
	Н	_
	\vdash	
		—
	$\vdash \vdash$	
		_
CORRES CONTROL	x	¥
Admin. Rec.	X	<u>~</u>
ERM Trooks	-	_
FRM Track'g	ш	_

CLASSIFICATION:

UCNI	\Box
UNCLASSIFIED	
CONFIDENTIAL	
SECRET	

AUTHORIZED CLASSIFIER
DOCUMENT CLASSIFICATION
REVIEW WAIVER PER
CLASSIFICATION OFFICE

IN REPLY TO RFP CC NO:

ACTION ITEM STATUS

OPEN OCICSED

PARTIL

LTR APPROVALS:

MB A!

CRIG & TYPIST INITIALS

ECM A TYPIST INITIALS

ECM A TYPIST INITIALS

SEGEG ROCKY FLATS

EG&G ROCKY FLATS, INC.
ROCKY FLATS PLANT, P.O. BOX 464, GOLDEN, COLORADO 80402-0464 • (303) 966-7000

March 4, 1993

93-RF-2735

Richard J. Schassburger
Acting Director
Environmental Restoration Division
DOE, RFO

Attn: J. Pepe

RELOCATION OF SOIL BORING AT IHSS 133.5 - MBA-016-93

Upon approval of Technical Memorandum No. 7 (TM 7), Soil Boring Sampling Plan -- Ash Pits, Incinerator and Concrete Wash Pad, the exact location of the borings were located in the field. One of the borings in IHSS 133.5 (Incinerator Area) was initially sited directly under a north-south 115 kv power line, and three borings located in IHSS 133.2 (Ash Pit) are about 25 to 30 feet south of an east-west trending 115 kv power line.

EG&G Rocky Flats, Inc. (EG&G) Construction Management (CM) is responsible for clearing sites for buried pipelines, overhead obstructions, or other potential hazards, prior to intrusive activities. The three sites in IHSS 133.2 were evaluated by CM and it was determined that the power lines did not pose a problem. However, the boring site at IHSS 133.5 (westernmost of the two proposed borings in that IHSS) had to be relocated approximately 30 feet west and slightly north of the original location (see Figure 8 in TM 7), but is still well within the 133.5 IHSS boundary. The change in location for this boring should have no impact on the data objectives for this IHSS.

Public Service Company of Colorado (PSCO) has been notified of our intended drilling program along their easement in Operable Unit No. 5. EG&G has PSCO approval for this activity in OU 5.

If you have any questions regarding this transmittal, please contact E. C. Mast of Remediation Project Management at extension 8589.

M. B. Arndt

Director

Remediation Project Management

ECM:dmf

Orig. and 1 cc - R. J. Schassburger

cc:

F. R. Lockhart - DOE, RFO

ADMIN RECORD

A-0005-000181